

**WORK SURFACES USED IN RODENT  
PROCEDURES MUST BE EASILY  
DECONTAMINATED/SANITIZED OR  
COVERED BY IMPERVIOUS, DISPOSABLE  
DRAPES.**

**CORK BOARDS/STYROFOAM MAY ONLY BE  
USED FOR NECROPSY/NON-SURVIVAL  
PROCEDURES AND ONLY WHEN COVERED  
WITH A CLEAN, IMPERVIOUS, DISPOSABLE  
DRAPE**

SC #162.1  
Eff. 3/17